SAPC 24448 COPY | OF |

10 February 1958

Dear Dan:

In a conversation on 6 February, I discussed with George K. the advisability of adding slack loops or elevators to the two negative machines. We find that the absence of these elevators leads to damage of the original films in the form of scratches, static marks and wrinkled edges. To date, this damage has been small but there is a potential for really serious loss of critical material. We estimate that these will cost approximately each for two.

In accordance with a verbal approval received from George we are proceeding to add these devices and will charge the work to PO-660.

ELG/njm cc: J.L.B.

W.C.N.

E. L. G.

Low K

DOCUMENT NO. 3/1

FI DECLASSIFIED
CLASS, CHANGED TO: TS S C 201
NEXT ALMOW DATE:
AUTH: HR 70-2.1

DAST 081281 FEVEWER 010956 1

25X1

Approved For Release 2002/08/19 : CIA-RDP81B00878R000700030147-5